

**EAST Search History****EAST Search History (Interference)**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	(quadrature and excitation and reference and synchronous and auxiliary).clm.	USPAT; UPAD	OR	OFF	2009/11/19 09:19
L2	0	(quadrature and excitation and reference and synchronous and auxiliary and in-phase).clm.	USPAT; UPAD	OR	OFF	2009/11/19 09:24
L3	4	(quadrature and excitation and reference and synchronous and in-phase).clm.	USPAT; UPAD	OR	OFF	2009/11/19 09:24
L4	1	(impedance and quadrature and excitation and reference and synchronous and in-phase).clm.	USPAT; UPAD	OR	OFF	2009/11/19 09:27
L5	5	(impedance and quadrature and excitation and reference and synchronous and in-phase).clm.	US- PG PUB; USPAT; UPAD	OR	OFF	2009/11/19 09:54
L6	1	600/547.ccls. and (impedance and quadrature and excitation and reference and synchronous and in-phase).clm.	US- PG PUB; USPAT; UPAD	OR	OFF	2009/11/19 10:21

11/19/2009 10:59:15 AM

C:\Documents and Settings\rdanega\My Documents\EAST\Workspaces\bio

**imped.wsp**